

Bulusan Volcano's seismic monitoring network recorded five (5) volcanic earthquakes during the past 24 hours. Steaming activity could not be observed due to thick clouds covering the summit. Sulfur dioxide (SO₂) emission was measured at an average of 148 tonnes/day on October 26, 2016. Precise leveling data obtained on October 17-23, 2016 indicated inflationary changes of the edifice relative to August 2016. Inflation was also recorded by continuous GPS measurements as of 30 September 2016, indicating pressurization beneath the volcano edifice.

Alert Level 1 (abnormal) remains in effect over Bulusan Volcano. This indicates that hydrothermal processes are underway beneath the volcano that may lead to steam-driven or phreatic eruptions. Local government units and the public are reminded that entry into the 4-kilometer radius Permanent Danger Zone (PDZ) is strictly prohibited and that vigilance in the Extended Danger Zone (EDZ) must be exercised due to the increased possibilities of sudden and hazardous phreatic eruptions. Civil aviation authorities must also advise pilots to avoid flying close to the volcano's summit as ash from any sudden phreatic eruption can be hazardous to aircraft. Furthermore, people living within valleys and along river/stream channels especially on the southeast, southwest and northwest sector of the edifice should be vigilant against sediment-laden stream flows and lahars in the event of heavy and prolonged rainfall. DOST-PHIVOLCS is closely monitoring Bulusan Volcano's condition and any new development will be communicated to all concerned stakeholders.

- [adapazari escort](#)
- [afyon escort](#)
- [agva escort](#)
- [akcay escort](#)
- [aksaray escort](#)
- [alanya escort](#)
- [amasya escort](#)