

Kanlaon Volcano's seismic monitoring network recorded two (2) volcanic earthquakes during the past 24 hours. Degassing at the active vents could not be observed due to thick clouds covering the summit. Ground deformation data from continuous GPS measurements indicate inflation of the edifice since December 2015. Sulfur dioxide (SO₂) emission was measured at an average of 1 tonne per day on September 6, 2017.

Alert Level 1 status prevails over Kanlaon Volcano, which means that it is at an abnormal condition and has entered a period of unrest. The local government units and the public are strictly reminded that entry into the 4-kilometer radius Permanent Danger Zone (PDZ) is strictly prohibited due to possibilities of sudden and hazardous steam-driven or phreatic eruptions. Civil aviation authorities must also advise pilots to avoid flying close to the volcano's summit as ejecta from any sudden phreatic eruption can be hazardous to aircraft. DOST-PHIVOLCS is closely monitoring Kanlaon Volcano's activity and any new development will be relayed to all concerned.